



Fort Peck Theater - Exterior Restoration

Total Cost
\$77,400

Area:
10,650s.f.

Client:
Fort Peck Fine Arts Council

Location:
Fort Peck, MT



Fort Peck Theater's exterior wood siding and moldings on this circa 1943 historic structure had deteriorated substantially; beyond repair in many cases. With the aid of the original construction drawings from the Army Corp of Engineers we were able to replace all of the missing moldings exactly to their original specifications. As a part of this restoration we also reestablished the original exterior colors.

Fort Peck's summer theater program is becoming very successful and will continue to expand and grow in part due to the revitalized exterior with its striking color scheme.

*Architecture
Matters*



After
Renovation



Original
Structure

